

Inspection Report-2014 Maruti Swift VXI

Exterior

Body

| | | | |
|---|----|-----------------------------------|----|
| No Rusting on outer body panels. | No | Left Rear Door is repainted. | No |
| Right side pillar A, B & C has no damage and factory seal intact. | No | Left Rear Door is Repaired. | No |
| Left side pillar A, B & C has no damage and factory seal intact. | No | Dickie is Repainted. | No |
| Front bumper is repainted. | No | Hood is Repainted. | No |
| Back bumper is repainted. | No | Right Fender is Repainted. | No |
| Right Front Door is repainted. | No | Right quarter Panel is Repainted. | No |
| Left Front Door is repainted. | No | Left quarter panel is repainted. | No |
| Right Rear Door is Repainted. | No | Left Rocker is repainted. | No |
| Right Rocker is repainted. | No | | |

EXTERIOR COMPONENTS

| | | | |
|--|-----|------------------------------|----|
| All door handles are operating properly. | Yes | Wipers are working properly. | No |
|--|-----|------------------------------|----|

GLASSES

| | |
|---|----|
| No scratch & cracks on windshields and windows. | No |
|---|----|

LIGHTS

| | |
|---|-----|
| Head lights, Tail lights and other lights functioning normally. | Yes |
| Head lights don't have any moisture formation. | Yes |

Interior

AIR CONDITIONER

| | |
|--|----|
| Vent air flow operate as designed. | No |
| Heating & Air Cooling condition operating as designed. | No |

BODY PANEL

| | |
|--|----|
| No scratch, dent or discoloration in interior body panels. | No |
| No Rusting in trunk floor. | No |

INTERIOR COMPONENTS

| | |
|--|-----|
| Interior door handles are operating properly. | Yes |
| Horn is functioning properly. | Yes |
| All knobs and switches are operating smoothly. | Yes |

SEATS

| | |
|---------------------------------|----|
| No stain, wear & tear in seats. | No |
|---------------------------------|----|

Engine

| | | | |
|--|----|---|-----|
| BATTERY | | | |
| <i>Battery condition is good.</i> | | | Yes |
| FIXTURES | | | |
| <i>No bodywork or rusting in the firewall.</i> | | | No |
| <i>No rusting or bodywork in apron.</i> | | | No |
| <i>Factory bolts and seals of bonnet frame are intact.</i> | | | Yes |
| HEALTH | | | |
| <i>Engine is intact and no overhauling done before.</i> | | | No |
| <i>No blowback observed in the Engine.</i> | | | No |
| <i>Engine is free of oil leakage.</i> | | | Yes |
| Road Test | | | |
| MALFUNCTION | | | |
| <i>No abnormal noise from engine.</i> | No | <i>No abnormal noise from gear box.</i> | No |
| <i>No abnormal noise from tyre.</i> | No | <i>No noise or leakage from axle.</i> | No |
| PEDAL | | | |
| <i>Transmission/ clutch operates properly with no slipping.</i> | | | No |
| <i>Brake is functioning properly with no slipping and free of noise.</i> | | | No |
| STABILITY | | | |
| <i>Vehicle doesn't pull to the side when brake is applied.</i> | | | Yes |
| <i>Vehicle drives straight on level surface.</i> | | | Yes |
| SUSPENSION | | | |
| <i>No abnormal noise or vibration from suspension.</i> | | | No |
| Tyres | | | |
| FRONT LEFT TYRE | | | |
| <i>No cut marks or hardening is observed in tyre.</i> | | | No |
| <i>No scratch, rusting and damage observed in rim.</i> | | | No |
| FRONT RIGHT TYRE | | | |
| <i>No cut marks or hardening is observed in tyre.</i> | | | No |
| <i>No scratch, rusting and damage observed in rim.</i> | | | No |
| REAR LEFT TYRE | | | |
| <i>No cut marks or hardening is observed in tyre.</i> | | | No |
| <i>No scratch, rusting and damage observed in rim.</i> | | | No |
| REAR RIGHT TYRE | | | |
| <i>No cut marks or hardening is observed in tyre.</i> | | | No |
| <i>No scratch, rusting and damage observed in rim.</i> | | | No |
| SPARE TYRE | | | |
| <i>Spare tyre is present.</i> | | | No |