

Inspection Report-2018 Maruti Swift Dzire LDI

Exterior

Body

| | | | |
|---|-----|-----------------------------------|-----|
| No Rusting on outer body panels. | Yes | Left Rear Door is repainted. | Yes |
| Right side pillar A, B & C has no damage and factory seal intact. | Yes | Left Rear Door is Repaired. | Yes |
| Left side pillar A, B & C has no damage and factory seal intact. | Yes | Dickie is Repainted. | Yes |
| Front bumper is repainted. | Yes | Hood is Repainted. | Yes |
| Back bumper is repainted. | Yes | Right Fender is Repainted. | Yes |
| Right Front Door is repainted. | Yes | Right quarter Panel is Repainted. | Yes |
| Left Front Door is repainted. | Yes | Left quarter panel is repainted. | Yes |
| Right Rear Door is Repainted. | Yes | Left Rocker is repainted. | Yes |
| Right Rocker is repainted. | Yes | | |

EXTERIOR COMPONENTS

| | | | |
|--|-----|------------------------------|-----|
| All door handles are operating properly. | Yes | Wipers are working properly. | Yes |
|--|-----|------------------------------|-----|

GLASSES

| | |
|---|-----|
| No scratch & cracks on windshields and windows. | Yes |
|---|-----|

LIGHTS

| | |
|---|-----|
| Head lights, Tail lights and other lights functioning normally. | Yes |
| Head lights don't have any moisture formation. | Yes |

Interior

AIR CONDITIONER

| | |
|--|-----|
| Vent air flow operate as designed. | Yes |
| Heating & Air Cooling condition operating as designed. | Yes |

BODY PANEL

| | |
|--|-----|
| No scratch, dent or discoloration in interior body panels. | Yes |
| No Rusting in trunk floor. | Yes |

INTERIOR COMPONENTS

| | |
|--|-----|
| Interior door handles are operating properly. | Yes |
| Horn is functioning properly. | Yes |
| All knobs and switches are operating smoothly. | Yes |

SEATS

| | |
|---------------------------------|-----|
| No stain, wear & tear in seats. | Yes |
|---------------------------------|-----|

Engine

| | | | |
|--|-----|---|-----|
| BATTERY | | | |
| <i>Battery condition is good.</i> | | | Yes |
| FIXTURES | | | |
| <i>No bodywork or rusting in the firewall.</i> | | | Yes |
| <i>No rusting or bodywork in apron.</i> | | | Yes |
| <i>Factory bolts and seals of bonnet frame are intact.</i> | | | Yes |
| HEALTH | | | |
| <i>Engine is intact and no overhauling done before.</i> | | | Yes |
| <i>No blowback observed in the Engine.</i> | | | Yes |
| <i>Engine is free of oil leakage.</i> | | | Yes |
| Road Test | | | |
| MALFUNCTION | | | |
| <i>No abnormal noise from engine.</i> | Yes | <i>No abnormal noise from gear box.</i> | Yes |
| <i>No abnormal noise from tyre.</i> | Yes | <i>No noise or leakage from axle.</i> | Yes |
| PEDAL | | | |
| <i>Transmission/ clutch operates properly with no slipping.</i> | | | Yes |
| <i>Brake is functioning properly with no slipping and free of noise.</i> | | | Yes |
| STABILITY | | | |
| <i>Vehicle doesn't pull to the side when brake is applied.</i> | | | Yes |
| <i>Vehicle drives straight on level surface.</i> | | | Yes |
| SUSPENSION | | | |
| <i>No abnormal noise or vibration from suspension.</i> | | | Yes |
| Tyres | | | |
| FRONT LEFT TYRE | | | |
| <i>No cut marks or hardening is observed in tyre.</i> | | | Yes |
| <i>No scratch, rusting and damage observed in rim.</i> | | | Yes |
| FRONT RIGHT TYRE | | | |
| <i>No cut marks or hardening is observed in tyre.</i> | | | Yes |
| <i>No scratch, rusting and damage observed in rim.</i> | | | Yes |
| REAR LEFT TYRE | | | |
| <i>No cut marks or hardening is observed in tyre.</i> | | | Yes |
| <i>No scratch, rusting and damage observed in rim.</i> | | | Yes |
| REAR RIGHT TYRE | | | |
| <i>No cut marks or hardening is observed in tyre.</i> | | | Yes |
| <i>No scratch, rusting and damage observed in rim.</i> | | | Yes |
| SPARE TYRE | | | |
| <i>Spare tyre is present.</i> | | | Yes |