

# Inspection Report-2017 Maruti Swift Dzire LXI

## Exterior

### Body

|   |    |                                   |    |
|---|----|-----------------------------------|----|
| No Rusting on outer body panels.                                  | No | Left Rear Door is repainted.      | No |
| Right side pillar A, B & C has no damage and factory seal intact. | No | Left Rear Door is Repaired.       | No |
| Left side pillar A, B & C has no damage and factory seal intact.  | No | Dickie is Repainted.              | No |
| Front bumper is repainted.  | No | Hood is Repainted.                | No |
| Back bumper is repainted.   | No | Right Fender is Repainted.        | No |
| Right Front Door is repainted.                                    | No | Right quarter Panel is Repainted. | No |
| Left Front Door is repainted.                                     | No | Left quarter panel is repainted.  | No |
| Right Rear Door is Repainted.                                     | No | Left Rocker is repainted.         | No |
| Right Rocker is repainted.  | No |                                   |    |

### EXTERIOR COMPONENTS

|  |     |                              |     |
|--|-----|------------------------------|-----|
| All door handles are operating properly. | Yes | Wipers are working properly. | Yes |
|--|-----|------------------------------|-----|

### GLASSES

|   |    |
|---|----|
| No scratch & cracks on windshields and windows. | No |
|---|----|

### LIGHTS

|   |     |
|---|-----|
| Head lights, Tail lights and other lights functioning normally. | Yes |
| Head lights don't have any moisture formation.                  | No  |

## Interior

### AIR CONDITIONER

|  |    |
|--|----|
| Vent air flow operate as designed.                     | No |
| Heating & Air Cooling condition operating as designed. | No |

### BODY PANEL

|  |    |
|--|----|
| No scratch, dent or discoloration in interior body panels. | No |
| No Rusting in trunk floor.                                 | No |

### INTERIOR COMPONENTS

|  |     |
|--|-----|
| Interior door handles are operating properly.  | Yes |
| Horn is functioning properly.                  | Yes |
| All knobs and switches are operating smoothly. | Yes |

### SEATS

|                                 |    |
|---------------------------------|----|
| No stain, wear & tear in seats. | No |
|---------------------------------|----|

## Engine

|  |    |   |     |
|--|----|---|-----|
| <b>BATTERY</b>   |    |   |     |
| <i>Battery condition is good.</i>  |    |   | Yes |
| <b>FIXTURES</b>  |    |   |     |
| <i>No bodywork or rusting in the firewall.</i>                           |    |   | No  |
| <i>No rusting or bodywork in apron.</i>                                  |    |   | No  |
| <i>Factory bolts and seals of bonnet frame are intact.</i>               |    |   | No  |
| <b>HEALTH</b>  |    |   |     |
| <i>Engine is intact and no overhauling done before.</i>                  |    |   | No  |
| <i>No blowback observed in the Engine.</i>                               |    |   | No  |
| <i>Engine is free of oil leakage.</i>                                    |    |   | Yes |
| <b>Road Test</b>   |    |   |     |
| <b>MALFUNCTION</b>   |    |   |     |
| <i>No abnormal noise from engine.</i>                                    | No | <i>No abnormal noise from gear box.</i> | No  |
| <i>No abnormal noise from tyre.</i>                                      | No | <i>No noise or leakage from axle.</i>   | No  |
| <b>PEDAL</b>   |    |   |     |
| <i>Transmission/ clutch operates properly with no slipping.</i>          |    |   | Yes |
| <i>Brake is functioning properly with no slipping and free of noise.</i> |    |   | No  |
| <b>STABILITY</b>   |    |   |     |
| <i>Vehicle doesn't pull to the side when brake is applied.</i>           |    |   | Yes |
| <i>Vehicle drives straight on level surface.</i>                         |    |   | Yes |
| <b>SUSPENSION</b>  |    |   |     |
| <i>No abnormal noise or vibration from suspension.</i>                   |    |   | No  |
| <b>Tyres</b>   |    |   |     |
| <b>FRONT LEFT TYRE</b>   |    |   |     |
| <i>No cut marks or hardening is observed in tyre.</i>                    |    |   | No  |
| <i>No scratch, rusting and damage observed in rim.</i>                   |    |   | No  |
| <b>FRONT RIGHT TYRE</b>  |    |   |     |
| <i>No cut marks or hardening is observed in tyre.</i>                    |    |   | No  |
| <i>No scratch, rusting and damage observed in rim.</i>                   |    |   | No  |
| <b>REAR LEFT TYRE</b>  |    |   |     |
| <i>No cut marks or hardening is observed in tyre.</i>                    |    |   | No  |
| <i>No scratch, rusting and damage observed in rim.</i>                   |    |   | No  |
| <b>REAR RIGHT TYRE</b>   |    |   |     |
| <i>No cut marks or hardening is observed in tyre.</i>                    |    |   | No  |
| <i>No scratch, rusting and damage observed in rim.</i>                   |    |   | No  |
| <b>SPARE TYRE</b>  |    |   |     |
| <i>Spare tyre is present.</i>  |    |   | Yes |